Form 17 Seller Disclosure Statement Rev. 8/21

## SELLER DISCLOSURE STATEMENT IMPROVED PROPERTY

©Copyright 2021
Northwest Multiple Listing Service

51

52

Rev. 8 Page						COVED PRO	PERTY	140	ALL R	GHTS	RESERV	ED	
SELL		LANA	A.	HENR	4								1
	742	Seller	1-11-000-00			Seller							- 1
dwelli	ngs in a	a residential com	nmon inf	terest communi	tv not s	subject to a pu	blic offering sta	lwellings up to fo tement, condomin Chapter 64.06 for	iums no	t subje	ect to a r	ction, oublic	3
Please "NA." the qu staten	e comp If the a uestion nent ar	answer is "yes" f (s) when you pr nd each attachn	ng form to any a rovide y nent. D	asterisked (*) ite our explanation elivery of the o	em(s), n(s). Fo disclosi	please explai or your protec ure statemen	n on attached : ction you must t must occur n	clearly does not a sheets. Please re date and initial ea ot later than five between Buyer an	fer to th ach pag (5) bus	e line e of th iness	number	(s) of	5 6 7 8 9
NOTIO	CE TO	THE BUYER											11
_90	03	MINTER	Ac	R			, CIT	OITION OF THE P		TY LC	CATED	AT	12 13
STAT LEGA	E <u>W</u>	A, ZIP 9 ESCRIBED ON	91.57 THE AT	, COUN	NTY IBIT A.	Steve	ns	("T	HE PR	OPER	TY") OF	R AS	14 15
ON S STATI THE D BY DE SELLE	SELLER EMENT DAY SE ELIVER ER DOI	R'S ACTUAL K T. UNLESS YOU ELLER OR SELL RING A SEPARA	NOWLE J AND S ER'S A TELY S OU A C	EDGE OF THI SELLER OTHEI GENT DELIVER SIGNED WRITT COMPLETED D	E PRO RWISE RS THIS EN STA ISCLOS	DPERTY AT AGREE IN V S DISCLOSUI ATEMENT OF SURE STATE	THE TIME S WRITING, YOU RE STATEMEN RESCISSION MENT, THEN	OR MATERIAL DE ELLER COMPLE HAVE THREE (3 IT TO YOU TO RE TO SELLER OR YOU MAY WAIVE MENT.	TES TI ) BUSIN SCIND SELLER	HIS C IESS THE A	DAYS FI AGREEM ENT. IF	ORE ROM IENT THE	16 17 18 19 20 21 22
LICEN	ISEE C		RTY. TH	IS INFORMATI	ION IS	FOR DISCLO		PRESENTATION AND IS NOT INTE					23 24 25
TO OI WITH BUILD THE I PROF	BTAIN OUT ING ING PROSE	AND PAY FOR LIMITATION, A NSPECTORS, O PECTIVE BUYE	THE SE ARCHIT ON-SIT IR AND IDE AP	ERVICES OF Q ECTS, ENGIN E WASTEWAT SELLER MAY PROPRIATE F	UALIF NEERS TER TH WISH PROVIS	IED EXPERT , LAND SU REATMENT I TO OBTAII	S TO INSPECT RVEYORS, P INSPECTORS, N PROFESSIO	OF THIS PROPE TTHE PROPERT PLUMBERS, ELE OR STRUCTUR NAL ADVICE OF ETWEEN THEM	Y, WHICE CTRICI RAL PES R INSPE	CH MA ANS, ST IN ECTIO	Y INCLU ROOFE SPECTO NS OF	JDE, ERS, DRS. THE	26 27 28 29 30 31 32
							Sell	ler 🖄 is / 🗆 is no	t occup	ying t	he Prop	erty.	33
		DISCLOSURE						2.50				0.78	34
*If y	ou ans	swer "Yes" to a publicly recorded	questio	n with an aster	risk (*),	please expla	in your answer	and attach docu	ments, i	f avail	able and	d not	
	TITLE	publicity recorded	u. II 1160	essary, use arr	attaciii	eu sneet.			YES	NO	DON'T KNOW	N/A	36 37 38
	A. Do	you have legal	authorit	ty to sell the pro	perty?	If no, please	explain		¥				39
,		title to the prope											40
										1			41
	(2)									Ø			42
										<b>3</b>			43
											×		44 45
							The state of the s			X			46
								the Buyer's use o		~	_	_	47
	the	property?								<b>25</b>			48
							naghannski kilonarik (1918) er - kun <u>s</u>	ght-of-way?				X	49
•	G. Ist	there any study.	survey	project, or notice	ce that	would advers	ely affect the ni	roperty?		*50			50

SELLER'S INITIALS

Date

SELLER'S INITIALS

\*I. Are there any zoning violations, nonconforming uses, or any unusual restrictions on the

\*H. Are there any pending or existing assessments against the property? ......

property that would affect future construction or remodeling?

Date

Form 17 Seller Disclosure Statement Rev. 8/21 Page 2 of 6

SELLER'S INITIALS

Date

SELLER'S INITIALS

Date

## SELLER DISCLOSURE STATEMENT IMPROVED PROPERTY

©Copyright 2021 Northwest Multiple Listing Service ALL RIGHTS RESERVED

(Continued)

2. WATI A. H	s there a boundary survey for the property?	YES 	NO	DON'T KNOW	N/A	54 55 56
2. WAT! A. H	Are there any covenants, conditions, or restrictions recorded against the property?		V			57
A. F	NOTICE TO BUYER: Covenants or deed restrictions based on race, creed, sexual orientation, or other protected class were voided by RCW 49.60.224 and are unenforceable. Washington aw allows for the illegal language to be struck by bringing an action in superior court or by the free recording of a restrictive covenant modification document. Many county auditor websites provide a short form with instructions on this process.					58 59 60 61 62
*	ER					63
* *	Household Water					64
*	(1) The source of water for the property is:   □ Private or publicly owned water system □ Private well serving only the subject property *□ Other water system					65 66
*	*If shared, are there any written agreements?				A	67
*	(2) Is there an easement (recorded or unrecorded) for access to and/or maintenance of the water source?			亙	1	68 69
*	(3) Are there any problems or repairs needed?SeeDisclosure_StAtement	.2				70
*	(4) During your ownership, has the source provided an adequate year-round supply of potable water?	X				71
*	If no, please explain:	938				72
	f(5) Are there any water treatment systems for the property?					73 74
*	'(6) Are there any water rights for the property associated with its domestic water supply, such as a water right permit, certificate, or claim?		Ø			75 76
*	(a) If yes, has the water right permit, certificate, or claim been assigned, transferred, or changed?				A	77
*	*(b) If yes, has all or any portion of the water right not been used for five or more successive years?				A	78
	(7) Are there any defects in the operation of the water system (e.g. pipes, tank, pump, etc.)?  See Disclosure Statement					79
	rrigation Water					80
10	(1) Are there any irrigation water rights for the property, such as a water right permit, certificate, or claim?				X	81 82
	*(a) If yes, has all or any portion of the water right not been used for five or more successive years?	П			×	83 84
	*(b) If so, is the certificate available? (If yes, please attach a copy.)				1	85
	*(c) If so, has the water right permit, certificate, or claim been assigned, transferred, or changed?				M	86
*	(2) Does the property receive irrigation water from a ditch company, irrigation district, or other entity?  If so, please identify the entity that supplies water to the property:	.0			M	87 88
						89
C. C	Outdoor Sprinkler System					90
	(1) Is there an outdoor sprinkler system for the property?	.□	M			91
*	(2) If yes, are there any defects in the system?	.0			×	92
*	(3) If yes, is the sprinkler system connected to irrigation water?	. 🗖			, ba	93
3. SEW	ER/ON-SITE SEWAGE SYSTEM					94
A. T	The property is served by:					95
	Public sewer system 🕏 On-site sewage system (including pipes, tanks, drainfields, and all other co	ompon	ent pa	arts)		96
_	Other disposal system  Please describe: <u>See Attached Disdoure Statement</u>					97
	Floade describe. The miniment of the property					98
	f public sewer system service is available to the property, is the house connected to	П	П		<b>76</b>	99
PM		.0	0	0	爲	

Form 17 Seller Disclosure Statement Rev. 8/21 Page 3 of 6

# SELLER DISCLOSURE STATEMENT IMPROVED PROPERTY

©Copyright 2021 Northwest Multiple Listing Service ALL RIGHTS RESERVED

(Continued)

	*C.	Is the property subject to any sewage system fees or charges in addition to those covered	YES	NO	DON'T	N/A	102
	<b>D</b>	in your regularly billed sewer or on-site sewage system maintenance service?	. 🗆	A			104
	υ.	If the property is connected to an on-site sewage system:  *(1) Was a permit issued for its construction, and was it approved by the local health					105
		department or district following its construction?			M		106 107
		(2) When was it last pumped?		-			
			$\overline{}$				108
		*(3) Are there any defects in the operation of the on-site sewage system?	শ্		Ц		109
		(4) When was it last inspected? 7-10-2025 Needs New					110
		By whom: Duane Johnson System			12		111
		(5) For how many bedrooms was the on-site sewage system approved? bedrooms			X		112
	E.	Are all plumbing fixtures, including laundry drain, connected to the sewer/on-site sewage system?	. 🗆		A		113 114
		If no, please explain:					115
	*F.	Have there been any changes or repairs to the on-site sewage system?	.🗖	Ø,			116
	G.	Is the on-site sewage system, including the drainfield, located entirely within the boundaries of the property?	.DE				117 118
		If no, please explain:					119
	*H.	Does the on-site sewage system require monitoring and maintenance services more frequently than once a year?	. 🗖		à		120 121
Wŀ	HICH	E: IF THIS RESIDENTIAL REAL PROPERTY DISCLOSURE IS BEING COMPLETED FOR N I HAS NEVER BEEN OCCUPIED, SELLER IS NOT REQUIRED TO COMPLETE THE QUESTIC CTURAL) OR ITEM 5 (SYSTEMS AND FIXTURES).	IEW C	ONS	TRUCTI IN ITE	ON M 4	122 123 124
4.	STF	RUCTURAL					125
	*A.	Has the roof leaked within the last 5 years? Lean-to Entrance leaked	13				126
		Has the basement flooded or leaked? Hat water heater exploded					127
	*C.	Have there been any conversions, additions or remodeling?	,BL				128
		*(1) If yes, were all building permits obtained?			K		129
	_	*(2) If yes, were all final inspections obtained?  Do you know the age of the house?	. 😃		×		130
	D.	If yes, year of original construction:	न्स्				131
	*⊏	The state of the s	rol .	_			132
		Has there been any settling, slippage, or sliding of the property or its improvements?					133
	г.	Are there any defects with the following: (If yes, please check applicable items and explain)  Decks  Exterior Walls	A,				134
		☐ Chimneys  ☐ Interior Walls ☐ Fire Alarms ☐ Chimneys  ☐ Windows ☐ Patio ☐ Ceilings  ☐ Slab Floors ☐ Driveways ☐ Pools ☐ Hot Tub ☐ Sauna ☐ Sidewalks  ☐ Outbuildings ☐ Fireplaces ☐ Garage Floors  ☐ Walkways  ☐ Siding ☐ Wood Stoves ☐ Elevators ☐ Incline Elevators ☐ Stairway Chair Lifts ☐ Wheelchair Lifts ☐ Other ☐ See Disclosure Sta	temo	ent			135 136 137 138 139 140 141 142 143
	*G.	Was a structural pest or "whole house" inspection done?	.□	A			144 145
	11	During your group his hardle and had an all the same his hard and a same his hardle and had a same his	heat!		_	_	146
	H. I.	During your ownership, has the property had any wood destroying organism or pest infestation?					147
	۱. J.	Is the attic insulated?		D			148 149
	J.	is the pasement insulated:		K		_	140

SELLER'S INITIALS Date

Form 17 Seller Disclosure Statement Rev. 8/21 Page 4 of 6

SELLER'S INITIALS

Date

SELLER'S INITIALS

Date

# SELLER DISCLOSURE STATEMENT IMPROVED PROPERTY

©Copyright 2021 Northwest Multiple Listing Service ALL RIGHTS RESERVED

(Continued)

5.	SYS	STEMS AND FIXTURES	YES	NO	DON'T	N/A	150
1200 1		If any of the following systems or fixtures are included with the transfer, are there any defects? If yes, please explain:			KINOW		151 152 153
		Electrical system, including wiring, switches, outlets, and service			0000	Ŏ O O O	154 155 156 157
		Appliances Sump pump	 	NO NO O	0000	BAOXO	
	*B.	If any of the following fixtures or property is included with the transfer, are they leased? (If yes, please attach copy of lease.)		_	_	A	162 163 164
		Security System:				A	165
		Tanks (type):				Ø	166
		Satellite dish:				X	167
		Other:				X	168
	*C.	Are any of the following kinds of wood burning appliances present at the property?			_	-	169
		(1) Woodstove?	U	<b>X</b>			170
		(3) Pellet stove?					171 172
		(4) Fireplace?		茶		_	173
		If yes, are all of the (1) woodstoves or (2) fireplace inserts certified by the U.S. Environmental			64		174
		Protection Agency as clean burning appliances to improve air quality and public health?				×	175
	D.	Is the property located within a city, county, or district or within a department of natural resources fire protection zone that provides fire protection services?	X	o.			176 177
	E.	Is the property equipped with carbon monoxide alarms? (Note: Pursuant to RCW 19.27.530, Seller					178
	-	must equip the residence with carbon monoxide alarms as required by the state building code.)					179
	F.	Is the property equipped with smoke detection devices?		×			180 181 182
	G.	Does the property currently have internet service?	X.				183
		Provider: Broad Ban - New Beam					184
6.	HOI	MEOWNERS' ASSOCIATION/COMMON INTERESTS					185
	A.	Is there a Homeowners' Association?				X	186 187 188
	В	Are there regular periodic assessments?	П			M	189
	О.		🖵		_	JOL	110000
		\$per □ month □ year □ Other:					191 192
	*C.	Are there any pending special assessments?				De	193
		Are there any shared "common areas" or any joint maintenance agreements (facilities such as walls, fences, landscaping, pools, tennis courts, walkways, or other areas					194 195
		co-owned in undivided interest with others)?	•			X	196
7.		/IRONMENTAL					197
		Have there been any flooding, standing water, or drainage problems on the property that affect the property or access to the property?		A			198 199
		Does any part of the property contain fill dirt, waste, or other fill material?					200
		Is there any material damage to the property from fire, wind, floods, beach movements, earthquake, expansive soils, or landslides?			×		201 202
		Are there any shorelines, wetlands, floodplains, or critical areas on the property?		M			203
	*E.	Are there any substances, materials, or products in or on the property that may be environmental concerns, such as asbestos, formaldehyde, radon gas, lead-based paint, fuel or chemical storage tanks, or contembated seil or water?	<b>W</b>		-	_	204 205
	*F	storage tanks, or contaminated soil or water?					206
0/	4	7-14-2025		M			207

Form 17 Seller Disclosure Statement Rev. 8/21 Page 5 of 6

# SELLER DISCLOSURE STATEMENT IMPROVED PROPERTY

©Copyright 2021 Northwest Multiple Listing Service ALL RIGHTS RESERVED

Page	5 of	6	(Continued)	milentus ele	i in Total			
				YES	NO	DON'T KNOW	N/A	208 209
	*G.	ls t	here any soil or groundwater contamination?	.□		X		210
	*H.	Are	there transmission poles or other electrical utility equipment installed, maintained, or					211
		bur	ied on the property that do not provide utility service to the structures on the property?	. 🗆		X		212
	*1.	Ha	s the property been used as a legal or illegal dumping site?	. 🗆	<b></b>	X		213
	*J.	Ha	s the property been used as an illegal drug manufacturing site?		B			214
	*K.	Are	there any radio towers in the area that cause interference with cellular telephone reception?	. 🗆		Ø		215
8.	LE/	AD E	BASED PAINT (Applicable if the house was built before 1978).					216
			sence of lead-based paint and/or lead-based paint hazards (check one below):					217
			Known lead-based paint and/or lead-based paint hazards are present in the housing (explain).					218
		X	Seller has no knowledge of lead-based paint and/or lead-based paint hazards in the housing					219 220
	В.		cords and reports available to the Seller (check one below):					221
			Seller has provided the purchaser with all available records and reports pertaining to					222
			lead-based paint and/or lead-based paint hazards in the housing (list documents below).					223
								224
		Á	Seller has no reports or records pertaining to lead-based paint and/or lead-based paint hazards in	the h	ousin	g.		225
9.	MA	NUF	ACTURED AND MOBILE HOMES					226
	If th	e pr	operty includes a manufactured or mobile home,					227
	*A.	Did	you make any alterations to the home?				X	228
		If y	es, please describe the alterations:					229
			any previous owner make any alterations to the home?				02	230
	*C.	lf a	Iterations were made, were permits or variances for these alterations obtained?				X	231
10.	FUI	LL D	ISCLOSURE BY SELLERS					232
	A.		ner conditions or defects:					233
		^Ar	e there any other existing material defects affecting the property that a prospective er should know about?	d				234
	D		ification		_	_	_	235
	Ъ.		e foregoing answers and attached explanations (if any) are complete and correct to the best of	Seller	's kno	owledge	and	236
		Sel	ler has received a copy hereof. Seller agrees to defend, indemnify and hold real estate licens	ees ha	armle	ss from	and	238
	-		ainst any and all claims that the above information is inaccurate. Seller authorizes real estate licen by of this disclosure statement to other real estate licensees and all prospective buyers of the prope		if any	, to deliv	er a	239 240
	4	,00		ity.				240
(	Ta	Se	ller Date Seller			Dat		241
			O Suit School			Dat	C	
16.11								
If the	ans	wer a) of	is "Yes" to any asterisked (*) items, please explain below (use additional sheets if necessary). the question(s).	. Plea	se re	fer to the	e line	242 243
	(-	,						
								244 245
								246
								247
								248

Form 17 Seller Disclosure Statement Rev. 8/21 Page 6 of 6

SELLER'S INITIALS

## SELLER DISCLOSURE STATEMENT IMPROVED PROPERTY

©Copyright 2021 Northwest Multiple Listing Service ALL RIGHTS RESERVED

(Continued)

#### II. NOTICES TO THE BUYER 257 1. SEX OFFENDER REGISTRATION 258 INFORMATION REGARDING REGISTERED SEX OFFENDERS MAY BE OBTAINED FROM LOCAL LAW ENFORCEMENT 259 AGENCIES. THIS NOTICE IS INTENDED ONLY TO INFORM YOU OF WHERE TO OBTAIN THIS INFORMATION AND IS NOT 260 AN INDICATION OF THE PRESENCE OF REGISTERED SEX OFFENDERS. 261 2. PROXIMITY TO FARMING/WORKING FOREST 262 THIS NOTICE IS TO INFORM YOU THAT THE REAL PROPERTY YOU ARE CONSIDERING FOR PURCHASE MAY LIE IN 263 CLOSE PROXIMITY TO A FARM OR WORKING FOREST. THE OPERATION OF A FARM OR WORKING FOREST 264 INVOLVES USUAL AND CUSTOMARY AGRICULTURAL PRACTICES OR FOREST PRACTICES, WHICH ARE PROTECTED 265 UNDER RCW 7.48.305, THE WASHINGTON RIGHT TO FARM ACT. 266 3. OIL TANK INSURANCE 267 THIS NOTICE IS TO INFORM YOU THAT IF THE REAL PROPERTY YOU ARE CONSIDERING FOR PURCHASE UTILIZES 268 AN OIL TANK FOR HEATING PURPOSES, NO COST INSURANCE MAY BE AVAILABLE FROM THE POLLUTION LIABILITY 269 INSURANCE AGENCY. 270 III. BUYER'S ACKNOWLEDGEMENT 271 1. BUYER HEREBY ACKNOWLEDGES THAT: 272 A. Buyer has a duty to pay diligent attention to any material defects that are known to Buyer or can be known to Buyer by 273 utilizing diligent attention and observation. 274 The disclosures set forth in this statement and in any amendments to this statement are made only by the Seller and 275 not by any real estate licensee or other party. 276 Buyer acknowledges that, pursuant to RCW 64.06.050(2), real estate licensees are not liable for inaccurate information 277 provided by Seller, except to the extent that real estate licensees know of such inaccurate information. 278 This information is for disclosure only and is not intended to be a part of the written agreement between the Buyer and Seller. 279 Buyer (which term includes all persons signing the "Buyer's acceptance" portion of this disclosure statement below) has 280 received a copy of this Disclosure Statement (including attachments, if any) bearing Seller's signature(s). 281 F. If the house was built prior to 1978, Buyer acknowledges receipt of the pamphlet Protect Your Family From Lead in Your Home. 282 DISCLOSURES CONTAINED IN THIS DISCLOSURE STATEMENT ARE PROVIDED BY SELLER BASED ON SELLER'S 283 ACTUAL KNOWLEDGE OF THE PROPERTY AT THE TIME SELLER COMPLETES THIS DISCLOSURE. UNLESS BUYER 284 AND SELLER OTHERWISE AGREE IN WRITING, BUYER SHALL HAVE THREE (3) BUSINESS DAYS FROM THE DAY 285 SELLER OR SELLER'S AGENT DELIVERS THIS DISCLOSURE STATEMENT TO RESCIND THE AGREEMENT BY 286 DELIVERING A SEPARATELY SIGNED WRITTEN STATEMENT OF RESCISSION TO SELLER OR SELLER'S AGENT. YOU 287 MAY WAIVE THE RIGHT TO RESCIND PRIOR TO OR AFTER THE TIME YOU ENTER INTO A SALE AGREEMENT. 288 BUYER HEREBY ACKNOWLEDGES RECEIPT OF A COPY OF THIS DISCLOSURE STATEMENT AND ACKNOWLEDGES 289 THAT THE DISCLOSURES MADE HEREIN ARE THOSE OF THE SELLER ONLY, AND NOT OF ANY REAL ESTATE 290 LICENSEE OR OTHER PARTY. 291 292 Buyer Date Buye Date 293 2. BUYER'S WAIVER OF RIGHT TO REVOKE OFFER 294 Buyer has read and reviewed the Seller's responses to this Seller Disclosure Statement. Buyer approves this statement and 295 waives Buyer's right to revoke Buyer's offer based on this disclosure. 296 297 Buyer Date Buyer Date 298 3. BUYER'S WAIVER OF RIGHT TO RECEIVE COMPLETED SELLER DISCLOSURE STATEMENT 299 Buyer has been advised of Buyer's right to receive a completed Seller Disclosure Statement. Buyer waives that right. 300 However, if the answer to any of the questions in the section entitled "Environmental" would be "yes," Buyer may not waive 301 the receipt of the "Environmental" section of the Seller Disclosure Statement. 302 303 Buyer Buyer Date 304 7-14-2025

SELLER'S INITIALS

Date

### Property Disclosure

- I requested a septic pump and learned that I actually have two separate septic systems (one for each side of the house) both of which are very small, old and not adequate for the house. The Septic on the side with the apricot trees was pumped October of 2022, but because the drain-field is not working, the septic only collects.
- 2. Fence is deteriorating: wooden stakes are rotting and many are missing; horizontal panels are warped. The "lawn" is infested with yellow clover which forms wide mats and hinders grass. Bind-weed (wild morning glory) was in the lawn when property was purchased and has roots over five feet deep, even under the foundation of the house.
- 3. The double-wide concrete driveway is cracked, deteriorating (crumbling), and very uneven. It starts at the street and runs along the side of the house all the way to the covered-patio at the back of the house.
- 4. Half of Exterior (the original house) is covered in Asbestos tiles, painted white. The rest of the house has weather-proof temporary paneling, some of it painted white
- 5. The foundation of the house, particularly along the driveway, is crumbling and several holes have allowed cats or rodents to crawl under the house. (Approximately 2022, a raccoon made its home under the kitchen and could be heard chewing on the floor-board and joists.)
- 6. Front sidewalk has a section that has sunk due to ants undermining the supporting soil.
- 7. In 2009, the metal roof over cedar shingles was removed. Everything was removed down to the rafters. Four-inch pink fiberglass insulation was placed over the rafters, and new plywood, tar paper, and composition shingles were installed. Three roof-vents were cut in the north side of the roof.
- 8. Metal front door has sun-faded.
- 9. The Entrance is made of painted plywood with no finishing material (like paneling, or shingles). It was extended from the front wall of the house and not properly attached to the front wall. There has been water damage to the ceiling of entrance, coat closet, and adjoining wall of front bedroom. Clear caulk was added without cleaning the crack which existed between the roof of entrance and exterior front wall of house.
- 10. The Entrance has a "coat" closet. Entrance is plywood structure and not insulated.
- 11. The floor of entrance is natural rock set in concrete, but the distance between front door and living-room door was not leveled, so rock slabs are loose and uneven.
- 12. Living room windows were changed in 2009 by Rural Resources/Avista Energy Assistance. Single-hung, double-pane, vinyl windows were installed and fiberglass insulation inserted into the wall above, beside, and under the window frame.
- 13. The Living room is paneled in tongue-and-groove natural wood knotty-pine.
- 14. The wall-to-wall tight-looped carpet was in the house when we purchased in 2005. It had several burned spots, (due to the house having been unoccupied for a year) and those have not changed.
- 15. The outlets in the Living room are not all grounded due to wiring being inaccessible in a brick wall.
- 16. The Entrance, Front bedroom, and Middle Bedroom do not have electricity due to a "dead" line in the attic, which is partly inaccessible because the "spider" or junction box are under the attic floor. The problem originated in 2019 with a flickering light fixture in the middle Bedroom. Current owner was not home when the husband (now deceased) was in the room and using the light. The wiring supplying the light fixture sparked and ruined the light fixture. The electric line has been dead ever since then.
- 16. The Electric Panel in the basement has too many lines and switches for the wattage demand of modern living: computers, appliances, numerous outlets.
- 17. Because of the crumbling foundation, there are visible cracks above the door of the Middle Bedroom, and the door cannot close. It is obvious that the door frame has shifted.

### Page 2 Property Disclosure Statement

- 18. The plumbing in the Bathroom between Master Bedroom and Middle Bedroom does not work properly.

  Owner has been told that it is not properly vented. Either the toilet or the tub can be used, but if the toilet is flushed while the tub is full, the line blocks and can not handle the water. The tub has always drained very slowly.
- 19. At some unknown time before December 2005, the Master Bedroom was expanded approximately six feet and a closet was built onto the concrete pad of the adjacent Covered Patio. No foundation work was done under the concrete pad, so the weight of the closet caused that part of the house to sink approximately six inches. In 2008, the concrete driveway was cut out and a huge hole was discovered between a flowerbed outside the Patio and running to the driveway. A proper foundation was formed to support the closet and corner of the house and five cubic yards of concrete was pumped under the Patio to fill the hole that had developed.
- 20. A former owner installed mirrored doors on the closet which added to the weight of the closet. The doors are so heavy, and the slant of the floor make the doors very difficult to maneuver. The closet is twelve feet long by thirty-three inches wide, and the doors cover the six-foot opening.
- 21. The formal Dining Room has a built-in storage area which was built around an old brick chimney (or concrete block?). The thin veneer doors have warped and do not close or open properly.
- 22. An Addition was constructed to the original house which was made into a Family room, a Bathroom, a Kitchen, and a Laundry area. Owner does not know when the addition was created. We were told by previous owner that the Kitchen was remodeled previous to 2004.
- 23. Whenever the Addition was constructed, the roof was given only a four-inch pitch (nearly flat). When the original metal roof was removed from the main part of the house, the roof was not removed from the Addition. Instead, rafters were built over the metal roof, and composition shingles were installed.
- 24. One wall of the Family room is mainly brick from an old "open" fireplace. At an unknown time, a metal "Aladdin Valley" wood-burning insert was installed. The metal of the insert is very thick and gets very hot! The air-intake fan no longer works well, and the fire inside does not have adequate air-flow. There is an exhaust pipe from the top of the insert up into the old fireplace chimney, but the design of the stove allows ashes to flow into the room from the top of the wood insert.
- 25. In 2005, when property was purchased by current owner, there were eight non-open-able windows with wooden frames. In 2009, those windows were removed to find the roof was sitting on those window frames, and the frames were sitting directly on the floorboards (with no foundation under neath). Proper "header" and "footer" were installed as well as the current open-able windows.
- 26. The three windows (the large picture window in the middle, and the two smaller windows) were purchased from a discount (thrift) store and were known to be factory rejects. The large picture window has a stain inside the double pane and cannot be cleaned. The smaller window (close to bathroom), has an interior problem. The rails are loose and have to be held in place if the window is opened. Since the floor is uneven, the windows are very difficult to open or close.
- 27. The Bathroom (off the Family room) has a wall heater and thermostat. Since the thermostat and heater are set into an exterior wall, the heater runs almost continually until the thermostat registers warmth in the wall instead of in the air-space of the Bathroom.
- 28. The window in the Bathroom was not set in the wall, but added to the outside of the exterior wall.
- 29. The Bathroom ceiling light fixture and fan are not vented to the outside because of the "double" roof.
- 30. The Fluorescent Light fixtures in the Kitchen were changed in 2012. They were purchased from Walmart and the available light tubes no longer match the ballasts, so the light above the stove flickers.
- 31. The Kitchen cabinets were new in 2003 or 2004 (?) when the Kitchen was remodeled.
- 32. The Sears Refrigerator was purchased in 2018 and works great. The deceased husband used the ice-maker continually, it has not been used since May, 2021.

### Page 3 Property Disclosure Statement

- 33. Their is also an installed dishwasher which current owner never used.
- 34. In July, 2020, a Jen-Air stove was removed (including the fan under the floor) and an Amana Electric Range was put in its place. The Amana has a Self-cleaning oven and four coil-burners. The Stabilizing Bracket was not installed, because of unusual wall-covering / Splash-board behind stove.
- 35. Also in 2020, a Kenmore Elite Top-Loading Clothes Washer was purchased and is staying with the house, along with the 1998 Frigidaire Clothes Dryer.
- 36. Between the Master Bedroom and the Dining Room is a stairway. From the Dining Room, the stairs go down into a small basement adjoining the crawl space. The stairs are steep and the railing is unstable. This space contains the Electric Panel (which contains too many circuits), the Hot Water Heater (purchased in 2012), as well as the Water Softening Unit (which has become contaminated with a green, bubbly mold which forms on the surface of the containment tank). There are two openings into the Crawl Space under the Original House. Both openings have been closed off with plywood and screws (to stop cold air in winter) but can easily be removed. From the hallway at the end of the Dining Room, the stairway leads up to the attic which covers the length and width of the original house. This stairway has varying width steps, but a solid railing.
- 37. Over the Front Entrance, in the attic, previous owner finished a Bedroom with a window, drywall, electric outlet, and a ceiling light. This space is approximately 13 feet long by 8 feet wide and carpeted. The center of the attic (21 feet by 9 feet) has hardwood flooring. Current owner added a 6' x 5' walk-in closet (untreated plywood with plastic wallpaper) as well as electric wiring and four outlets and three light fixtures. The attic electricity was properly grounded.
- 38. Four-inch Pink fiberglass was laid over the lath-and-plaster under the eaves and loose floor-board was added over the beams for storage on both sides of the original house attic.
- 39. There are two doorways out the back of the house. One out of the Kitchen onto the Patio, and the other at the top of the stairway going into the basement, beside the "closet" addition.
- 40. Facing the Backdoor off the Kitchen is an out-building with two rooms but no door between the rooms. This was built with plywood exterior and drywall interior, no insulation, and a cedar-shingle roof covered with grooved metal panels. Both rooms have electricity (outlets) and ceiling light fixture. The larger room outlet by the door once overheated (fifteen years ago?) and damage is unknown. No damage occurred to the wall. Both rooms have windows on the sides. In 2008, current owner applied vinyl siding to three walls of this building.
- 41. A Sidewalk runs from the Covered Patio toward the out-building and the Alley. The concrete has holes and is crumbling. The gate at the alley is falling apart and the lumber in the privacy fence needs replacing.
- 42. The double-garage opens off the alley and has an electric door-opener which was installed 2008. There was a bare wire, old electric line (? nob and tooth) went from the roof of the Covered Patio out to the roof of the Garage to service three electric outlets and overhead fluorescent lights. Current owner installed new wiring and buried the line from the Covered Patio to the double-door opening on the side of the Garage. (The door was made of rough lumber, painted and has warped)
- 43. One-third of the length of the Garage was turned into a Shop years ago, with an entrance off the Patio. Since the roof of the Covered Patio connects with the Exterior wall of the Garage, snow-melt and rain run off the metal roof of Patio down the exterior wall of the Garage. Over the years, extensive mold and water damage have rotted the wall around the doorway.
- 44. Under that "shop" is a concrete-walled area underground supposedly built in 1940 as a "bomb shelter". This area collects water (sometimes 3 6 inches) even though current owner tried to paint it with water-proof paint. The entrance to this is by opening a floor-level plywood which is hinged to concrete walls, the underside collects moisture in winter and gets moldy. The solid concrete stairs are very deep and varying depths.

## Page 4 Property Disclosure Statement

- 45. At an unknown time in the past (2015?), the hot water heater that was in the property when property was purchased, started malfunctioning and blew hot water all over the small basement room. It was discovered that one heating element had burned out, and the remaining heating element was over working to heat the tank of water. A new hot water heater was purchased and installed and there has not been water in that basement room since. Since the room does not get fresh air or sunlight, the mold and mildew that started then has continued to ruin the storage area
- 46. The property line between 903 Minter and 907 Minter is obscure. Previous owners of 903 built the Garage and a Privacy Fence inside the property lines. The current owner of 907 uses all the land up to the privacy fence for a garden and claims the fence is on the property line even though the water meter for 903 is three feet outside the fence. In the alley, the old telephone connection is also three feet outside the Garage wall. Wanting to be good neighbors, this dispute was never taken to public court, and no official action was taken.
- 47. In the bathroom off the Family Room, the shut-off valve for the toilet does not work. This was discovered when the inside plumbing was replaced in April 2024. The float system inside the tank was replaced on both toilets, including the flap closures.