

139 – Hot Tub: Does not work, multiple leaks in water piping.

140 – Outbuildings: Hot Tub Building needs to be demolished, black mold throughout. Sidewalks: All sidewalks need to be replaced.

142 – Woodstove: This is the only source of heat, has been previously repaired but is currently showing new signs of fatigue.