



Serving Pend Oreille County and Little Pend Oreille Lakes

Hortons Enterprises
Septic Inspection Form
(509)421-0234
17872 Hwy 31, Metaline Falls, WA 99153

Date 9-29-22 Inspected By Floyd

Customer Robin C Lyons

Address 398462 Hwy 20
Cusick Wa

Tank Capacity 1000 gal Tank Condition good

System Type Gravity Flow

Comments Pumped out the tank. Its a
2 chamber tank with 2 lids. The
inlet and outlet down spouts were
present and working. The drain field
accepted good water flow. System
should be pumped every 3-5 years
under normal use.

Hortons Enterprises is not liable for any current or future septic issues related to this inspection. All statements made in this inspection are true and accurate to the best of our knowledge at the time of the inspection.